

ArcelorMittal – Indiana Harbor

Inspected the facility on 2/9/17 w/ John Jurevis & Sangsook Choi. Witnessed oil sheen on the surface of canal at Outfall 001 but not Outfalls 009 & 010.

To Do:

- Determine (with you) our path forward and relay that determination to Mike Beslow (Superfund) and Naeha Dixit (ORC), who are waiting to hear from us before figuring out what they will do.
- Draft the inspection report.
- Review results of sampling conducted by Mike Beslow in mid-Jan. 2017.
- Determine whether another inspection (CEI) should be conducted based on me not being able to accomplish all I was planning to during the 2/9 inspection due to our facility contact having a prior engagement.

Ex. 5 DP / Ex. 7(A)

Ex. 5 DP / Ex. 7(A)

Ex. 5 DP / Ex. 7(A)